USNRC REGION II
ATLANTA, GEORGIA

TELECOPY

81 OCT 28 A10 : 00

October 27, 1981

Mr. J. P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
101 Marietta St., Suite 3100
Atlanta, GA 30303

Re: Docket 50-302
Licensee: DPR-72

This will confirm a report to Mr. V. Brownlee of your office on October 27, 1981 at 1440.

At 1030 on October 27, 1981, notification was received that a potential high energy pipe whip and/or jet impingement could cause a possible loss of safety-related systems and/or components.

The main steam lines supplying the turbine driven emergency feedwater pump have not been considered for High Energy Line Break Outside Containment (HELBOC).

Based on this notification, it was determined that this concern warrants reporting under Technical Specification 6.9.1.8.1.

There was no effect upon the health or safety of the general public.

A detailed report will follow within fourteen (14) days.

RECEIVED
NOV 02 1981
U.S. NUCLEAR REGULATORY COMMISSION

D. C. Poole
Nuclear Plant Manager
Florida Power Corporation
Crystal River Unit #3
Crystal River, FL 32629

Verified by:_____ at_____ on 27 October 1981.

/rc

REGIONAL DIRECTOR
DEPUTY DIRECTOR
ASSISTANT TO DIRECTOR
DIRECTOR, RRPI
DIRECTOR, EPOS
DIRECTOR, ENF/INV
DIRECTOR, ETI
PUBLIC AFFAIRS OFFICER

IE22
S
1
K0

8111030340 811027
PDR ADOCK 05000302
S PDR