NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

UPDATE REPORT - PREVIOUS
REPORT DATE: 10-02-78

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | I L D R S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T.
01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 3 7 (7) | 0 9 0 7 7 8 (8) | 1 0 1 7 7 8 (9)
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing surv. DIS 1600-11 (Press. Suppression Air Oper. Vlv. press sw. setpt.
03 ck.) valve 2-1601-24 failed to operate in the specified time limit required by T.S.
04 4.7.D.1.a, Table 3.7.1. Safety significance minimal because redundant (inboard) iso-
05 lation valve was operable and would have provided containment integrity within spec-
06 ified times as required. This is the first occurrence of this type at Dresden.
07
08 80
8 9

09 | SYSTEM CODE S D (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE V A L V O P (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)
8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 7 8 | — | SEQUENTIAL REPORT NO. 0 5 1 | / | OCCURRENCE CODE 0 3 | REPORT TYPE X | — | REVISION NO. 1
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURE P 3 4 0 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Probable cause-foreign matter lodged in solenoid operated 4 way valve thereby pre-
11 venting proper bleed off. Subsequent testing and external inspection revealed no
12 abnormalities. With exception to the initial valve operation all subsequent operations
13 were well within the specified times setforth in the Tech. Specs. Because of the
14 singular nature of the event no further actions are deemed necessary.
80
8 9

15 | FACILITY STATUS E (28) | % POWER 0 9 5 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Testing
8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA
8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA 7811240211
8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA
8 9 10 80

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY
8 9 10 68 69 80

NAME OF PREPARER Sigmund A Cieszkiewicz PHONE: X-222

JPO 917-926