NRC FORM 366 (7-77) U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LICENSEE CODE: N Y J A F 1 (2) LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 0 (3) LICENSE TYPE: 4 1 1 1 1 (4) CAT: (5)

CON'T 01 REPORT SOURCE: L (6) DOCKET NUMBER: 0 5 0 0 0 3 3 3 (7) EVENT DATE: 1 0 0 7 8 1 (8) REPORT DATE: 1 1 1 3 8 1 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, while conducting surveillance to satisfy TS Table 4.2-2,
03 Item 13, condensate storage tank level switch 23-LIS-75B, associated with HPCI
04 suction transfer was damaged and required repair. The other three (3) switches
05 performing the same function were operating normally. No significant hazard
06 existed.
07
08

09 SYSTEM CODE: S F (11) CAUSE CODE: D (12) CAUSE SUBCODE: Z (13) COMPONENT CODE: Z Z Z Z Z Z (14) COMP. SUBCODE: Z (15) VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR: 8 1 — SEQUENTIAL REPORT NO.: 0 7 3 / OCCURRENCE CODE: 0 3 REPORT TYPE: X — REVISION NO.: 1

ACTION TAKEN: X (18) FUTURE ACTION: G (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS (22): 0 0 0 0 ATTACHMENT SUBMITTED: N (23) NPRD-4 FORM SUB.: Y (24) PRIME COMP. SUPPLIER: Z (25) COMPONENT MANUFACTURER: Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Partial disassembly of the instrument enclosure, to allow observation of switch
11 action, caused a screw to catch and damage the insulation on a wire. Repair and
12 calibration restored the instrument to a fully operable status approximately five
13 (5) hours later. In addition, a precaution will be added to the procedure to
14 prevent recurrence.

15 FACILITY STATUS: E (28) % POWER: 0 7 0 (29) OTHER STATUS (30): NA METHOD OF DISCOVERY: B (31) DISCOVERY DESCRIPTION (32): Surveillance

16 ACTIVITY RELEASED: Z (33) CONTENT OF RELEASE: Z (34) AMOUNT OF ACTIVITY (35): NA LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES
17 NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION (39): NA

PERSONNEL INJURIES
18 NUMBER: 0 0 0 (40) DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE: Z (42) DESCRIPTION: NA

8111230438 811113
PDR ADOCK 05000333
S PDR

PUBLICITY
20 ISSUED: N (44) DESCRIPTION (45): NA NRC USE ONLY

NAME OF PREPARER W. Verne Childs PHONE: 315-342-3840