NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
0 1	LICENSEE CODE (2)	N C M G S 1
	LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
	LICENSE TYPE (4)	4 1 1 1 1
	CAT (5)	
CON'T 0 1	REPORT SOURCE (6)	L
	DOCKET NUMBER (7)	0 5 0 0 0 3 6 9
	EVENT DATE (8)	1 1 1 7 8 1
	REPORT DATE (9)	1 2 1 7 8 1

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While in mode 5, during performance of the annual fire protection audit in
0 3 accordance with T.S.6.5.2.9(I), 3 fire barriers were found breached. The
0 4 barriers were declared inoperable and hourly fire watches established per T.S.
0 5 3.7.11, which is reportable pursuant to T.S.6.9.1.13(b) and similar to previous
0 6 RO369/81-41. Since the plant was in cold shutdown and there were no fires in
0 7 any of the affected areas, the safe operation of the plant and the health and
0 8 safety of the public were unaffected by this incident.

Line	Field	Value
0 9	SYSTEM CODE (11)	A B
	CAUSE CODE (12)	C
	CAUSE SUBCODE (13)	Z
	COMPONENT CODE (14)	X X X X X X
	COMP. SUBCODE (15)	Z
	VALVE SUBCODE (16)	Z
LER/RO REPORT NUMBER (17)	EVENT YEAR	8 1
		—
	SEQUENTIAL REPORT NO.	1 8 4
		/
	OCCURRENCE CODE	0 3
	REPORT TYPE	L
		—
	REVISION NO.	0
	ACTION TAKEN (18)	B
	FUTURE ACTION (19)	Z
	EFFECT ON PLANT (20)	Z
	SHUTDOWN METHOD (21)	Z
	HOURS (22)	0 0 0 0
	ATTACHMENT SUBMITTED (23)	N
	NPRD-4 FORM SUB. (24)	N
	PRIME COMP. SUPPLIER (25)	L
	COMPONENT MANUFACTURER (26)	X 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 One barrier had fallen through its penetration, possibly due to its own weight.
1 1 Another barrier had a 4 inch diameter hole in the sheetrock wall which appeared
1 2 to have been knocked through. The final breaching involved a hole in a wall
1 3 which appeared to have been caused by water damage to the sheetrock wall. The
1 4 penetration was filled with fireproof foam and the bottom end covered, and the two holes were patched.

Line	Field	Value
1 5	FACILITY STATUS (28)	X
	% POWER (29)	0 0 0
	OTHER STATUS (30)	Mode 5
	METHOD OF DISCOVERY (31)	B
	DISCOVERY DESCRIPTION (32)	Annual fire protection audit
1 6	ACTIVITY RELEASED (33)	Z
	CONTENT OF RELEASE (34)	Z
	AMOUNT OF ACTIVITY (35)	N/A
	LOCATION OF RELEASE (36)	N/A
1 7	PERSONNEL EXPOSURES NUMBER (37)	0 0 0
	TYPE (38)	Z
	DESCRIPTION (39)	N/A
1 8	PERSONNEL INJURIES NUMBER (40)	0 0 0
	DESCRIPTION (41)	N/A
1 9	LOSS OF OR DAMAGE TO FACILITY TYPE (42)	Z
	DESCRIPTION (43)	N/A
2 0	PUBLICITY ISSUED (44)	N
	DESCRIPTION (45)	N/A
	NRC USE ONLY	

NAME OF PREPARER: Phillip B. Nardoci PHONE: (704) 373-7432

8112290442 811217
PDR ADOCK 05000369
S PDR