(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0 1] 4 C T M N S 2 (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) [ ] (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T [0 1] REPORT SOURCE L (6) 0 5 0 0 0 3 3 6 (7) 1 2 3 0 8 1 (8) 0 1 2 9 8 2 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0 2] While in mode 6 and during routine refueling operations it was observed that the

[0 3] surveillance procedure 2610C-1 requiring the cycling of the Auxiliary Feedwater

[0 4] Motor Operated Valves was not performed in the period of November 15, 1981 to

[0 5] November 22, 1981 as required by Technical Specification 4.7.1.2.a4. The unit was

[0 6] at 100% power during this time period. Similar LERs 76-32, 77-44, 77-51, 78-25,

[0 7] 81-35

[0 8] 80

7 8 9

[0 9] SYSTEM CODE C H (11) CAUSE CODE A (12) CAUSE SUBCODE A (13) COMPONENT CODE Z Z Z Z Z Z (14) COMP. SUBCODE Z (15) VALVE SUBCODE Z (16)

7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER EVENT YEAR 8 1 SEQUENTIAL REPORT NO. 0 4 5 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN Z (18) FUTURE ACTION X (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS (22) 0 0 0 0 ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB N (24) PRIME COMP. SUPPLIER Z (25) COMPONENT MANUFACTURER Z 9 9 9 (26)

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1 0] The cause of this incident was personnel error in not completing the surveillance

[1 1] requirement within the required interval. Since the Unit is presently in Mode 6

[1 2] there is no corrective action. The Operations Supervisor or his designee will

[1 3] verify completion of surveillance at least one day before the scheduled interval

[1 4] ends to prevent recurrence.

80

7 8 9

[1 5] FACILITY STATUS H (28) % POWER 0 0 0 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY A (31) DISCOVERY DESCRIPTION (32) Personnel Observation.

7 8 9 10 12 13 44 45 46 80

[1 6] ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

7 8 9 10 11 44 45 80

[1 7] PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION (39) NA

7 8 9 11 12 13 80

[1 8] PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION (41) NA

7 8 9 11 12 80

[1 9] LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION (43) NA

7 8 9 10 80

[2 0] PUBLICITY ISSUED N (44) DESCRIPTION (45) NA

68 69 80

NRC USE ONLY

8202050352 820129
PDR ADOCK 05000336
S PDR

J.M. Bergin PHONE 447-1791 ext. 4462