LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
01	LICENSEE CODE (2)	M A P S 1
01	LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
01	LICENSE TYPE (4)	4 1 1 1 1
01	CAT (5)	
CON'T 01	REPORT SOURCE (6)	L
01	DOCKET NUMBER (7)	0 5 0 - 0 2 9 3
01	EVENT DATE (8)	1 2 3 0 8 1
01	REPORT DATE (9)	0 1 2 6 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On 12/30/81, during a refuel outage, while investigating a cause for the LLRT failure
03 of AO-203-2A (Outboard MSIV), 2 of the 4 hold-down bolts on the poppet were found
04 to have been installed without lock plates. One of the bolts had started to back
05 out leading to the observed leakage of the valve. No adverse effects to public
06 health or safety can be attributed to this event.
07
08

Line 09	SYSTEM CODE (11)	CAUSE CODE (12)	CAUSE SUBCODE (13)	COMPONENT CODE (14)	COMP. SUBCODE (15)	VALVE SUBCODE (16)
	C D	A	C	V A L V E X	H	D

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 1	—	0 6 5	/	0 3	L	—	0

ACTION TAKEN (18)	FUTURE ACTION (19)	EFFECT ON PLANT (20)	SHUTDOWN METHOD (21)	HOURS (22)	ATTACHMENT SUBMITTED (23)	NPRD-4 FORM SUB. (24)	PRIME COMP. SUPPLIER (25)	COMPONENT MANUFACTURER (26)
G	H	Z	Z	0 0 0 0	N	N	N	A 5 8 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A failure to follow assembly procedures during a previous valve overhaul is the cause
11 of this event. A change to procedure 3.M.4.8 will be made to include a QC sign-off
12 to assure proper assembly prior to poppet closure in the valve body.
13
14

Line	Field	Value
15	FACILITY STATUS (28)	H
15	% POWER (29)	0 0 0
15	OTHER STATUS (30)	NA
15	METHOD OF DISCOVERY (31)	B
15	DISCOVERY DESCRIPTION (32)	LLRT Failure Inspection
16	ACTIVITY RELEASED (33)	Z
16	CONTENT OF RELEASE (34)	Z
16	AMOUNT OF ACTIVITY (35)	NA
16	LOCATION OF RELEASE (36)	NA
17	PERSONNEL EXPOSURES NUMBER (37)	0 0 0
17	TYPE (38)	Z
17	DESCRIPTION (39)	NA
18	PERSONNEL INJURIES NUMBER (40)	0 0 0
18	DESCRIPTION (41)	NA
19	LOSS OF OR DAMAGE TO FACILITY TYPE (42)	Z
19	DESCRIPTION (43)	NA
20	PUBLICITY ISSUED (44)	N
20	DESCRIPTION	NA
20	NRC USE ONLY	

8202090075 820126
PDR ADOCK 05000293
S PDR

NAME OF PREPARER G. G. Whitney PHONE: 617-746-7900