(7 77)

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0 1] | C T M N S 2 (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
[0 1] REPORT SOURCE | L (6) 0 5 0 0 0 3 3 6 (7) 0 1 0 6 8 2 (8) 0 2 0 1 8 2 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0 2] With the plant shutdown for refueling, fuses in inverters 2 and 6 blew resulting
[0 3] in loss of vital instrument panel VA-20 causing closure of the overpressure circuit
[0 4] for shut down cooling which caused valve 2-S1-652 to close. Shutdown cooling was
[0 5] restored in 7 minutes. The plant was operated in accordance with T.S.A.S. 3.9.8.2
[0 6] during this event. No similar LER's.
[0 7]
[0 8] 7 8 9 80

[0 9] 7 8
SYSTEM CODE: E C (11) 9 10
CAUSE CODE: E (12) 11
CAUSE SUBCODE: A (13) 12
COMPONENT CODE: C K T B R K (14) 13 18
COMP. SUBCODE: E (15) 19
VALVE SUBCODE: Z (16) 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 21 22 | — 23 SEQUENTIAL REPORT NO. 0 0 2 24 26 | / 27 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 | — 31 REVISION NO. 0 32

ACTION TAKEN: A (18) 33 FUTURE ACTION: Z (19) 34 EFFECT ON PLANT: Z (20) 35 SHUTDOWN METHOD: Z (21) 36 HOURS (22): 0 0 0 0 37 40 ATTACHMENT SUBMITTED: Y (23) 41 NPRD-4 FORM SUB.: N (24) 42 PRIME COMP. SUPPLIER: A (25) 43 COMPONENT MANUFACTURER: X 9 9 9 (26) 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1 0] A short circuited test lead caused a printed circuit to fail. The load was
[1 1] transferred from inverter 2 to inverter 6. A large current flow resulted, which
[1 2] blew the fuses in both inverters. A departmental memo was issued to all tech-
[1 3] nicians to check all leads prior to connection to test equipment.
[1 4] 7 8 9 80

[1 5] 7 8
FACILITY STATUS: H (28) 9
% POWER: 0 0 0 (29) 10 12
OTHER STATUS (30): NA 13 44
METHOD OF DISCOVERY: B (31) 45 46
DISCOVERY DESCRIPTION (32): Operator observation 80

[1 6] 7 8
ACTIVITY RELEASED: Z (33) 9
CONTENT OF RELEASE: Z (34) 10
AMOUNT OF ACTIVITY (35): NA 11 44
LOCATION OF RELEASE (36): NA 45 80

[1 7] 7 8
PERSONNEL EXPOSURES
NUMBER: 0 0 0 (37) 9 11
TYPE: Z (38) 12
DESCRIPTION (39): NA 13 80

[1 8] 7 8
PERSONNEL INJURIES
NUMBER: 0 0 0 (40) 9 11
DESCRIPTION (41): NA 12 80

[1 9] 7 8
LOSS OF OR DAMAGE TO FACILITY (43)
TYPE: Z (42) 9
DESCRIPTION: NA 10 80

[2 0] 7 8
PUBLICITY
ISSUED: N (44) 9
DESCRIPTION (45): NA 10 68

8202090098 820201
PDR ADOCK 05000336
S PDR

NRC USE ONLY | | | | | | | | | | 69 80

NAME OF PREPARER Steve Stadnick PHONE (203) 447-1791