No. 3-82-03/03L-0

Mr. R. C. Haynes
Administrator
U.S. Nuclear Regulatory
Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Haynes:

The following LER describes an operator error in replacing a curcuit breaker after a maintenance block. The applicable Technical Specification is 4.5.A.2.

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 PAPBS3 (2) 00-000000000 (3) 4111 1 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 REPORT SOURCE (6) 050-02787 (7) 041383 (8) 051382 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During surveillance testing, the "C" Core Spray Pump failed to start. Applicable Technical Specification is 4.5.A.2. The breaker was racked out on 3/29 for safety while valve maintenance was performed. The breaker was "racked in" on 4/5 after completion of maintenance, but a functional test was not performed.

09 SYSTEM CODE SF (11) CAUSE CODE A (12) CAUSE SUBCODE B (13) COMPONENT CODE CKTBRK (14) COMP. SUBCODE A (15) VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 003 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN H (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 0000 (22) ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. Y (24) PRIME COMP. SUPPLIER A (25) COMPONENT MANUFACTURER G080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Investigation determined the cause to be a mis-aligned pump breaker cell switch. After discovery, the breaker was re-racked and the surveillance test completed satisfactorily. The responsible operator was counseled regarding the need to verify operability of 4KV equipment each time a breaker is "racked in".

FACILITY STATUS E (28) % POWER 100 (29) OTHER STATUS (30) N/A METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION (32) Operator observation

ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES NUMBER 000 (37) TYPE Z (38) DESCRIPTION (39) N/A

PERSONNEL INJURIES NUMBER 000 (40) DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION (43) N/A

IE22 5011

PUBLICITY ISSUED N (44) DESCRIPTION (45) N/A

8205260029 5

NRC USE ONLY

NAME OF PREPARER M. J. Cooney PHONE: (215) 841-5020

GPO 917-924