LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M I D C C 1 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 5 (7) | 0 5 0 3 8 2 (8) | 0 6 0 1 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING NORMAL OPERATION, THE FLOW INDICATOR (SFR-201) FOR THE TURBINE GLAND SEAL LEAK
03 | OFF (GLSO) FAILED LOW. THE INSTRUMENTATION WAS DECLARED INOPERABLE AT 1830 HOURS ON
04 | MAY 3, 1982. CONTINUOUS FLOW MEASUREMENT IS REQUIRED BY TECHNICAL SPECIFICATION,
05 | APPENDIX B, 2.4.4.b AND TABLE 2.4-4 (AMENDMENT 26). PREVIOUS SIMILAR OCCURRENCES
06 | INCLUDE: 050-316/ 81-075,82-015,028.
07 |
08 |

09 | SYSTEM CODE M C (11) | CAUSE CODE B (12) | CAUSE SUBCODE A (13) | COMPONENT CODE I N S T R U (14) | COMP SUBCODE E (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 3 0 | / | OCCURRENCE CODE 0 4 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER X 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | THE FLOW INDICATING PROBE (SFR-201) WAS EXAMINED AND FOUND TO HAVE EXCESSIVE MOISTURE
11 | ON THE SENSING ELEMENT. THE MOISTURE WAS REMOVED, THE PROBE WAS REINSTALLED AND THE
12 | INDICATOR RETURNED TO NORMAL SERVICE AT 2010 HOURS ON MAY 3, 1982. INVESTIGATION
13 | IS CONTINUING INTO METHODS TO REDUCE THE MOISTURE IN THIS AREA.
14 |

15 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA (43)

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

8206070541 820601
PDR ADOCK 05000315
S PDR

NRC USE ONLY

NAME OF PREPARER R. A. Palmer PHONE 616-465-5901

GPO 917-926