NRC FORM 366 (7-77) U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

LER 82-9/3L

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | VTVYS1 (2) | 00-0000-00 (3) | 4111 1 (4) | (5)

LICENSEE CODE (9–14) LICENSE NUMBER (15–25) LICENSE TYPE (26–30) CAT (57–58)

CON'T 01 REPORT SOURCE L (6) | 05000271 (7) | 051382 (8) | 061182 (9)

DOCKET NUMBER (60–68) EVENT DATE (69–74) REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, Rx pressure indicator PI 2-3-55D indicated lower than redundant

03 indicators. The indication and trip point were drifting. The operator then imposed a

04 1/2 scram on Channel B per T. S. Table 3.1.1. There were no consequences to the health

05 and safety of the public. There were no previous reportable occurrences of this type.

06

07

08

09 SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE G (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE P (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 009 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN C (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER E229 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of this event was a degraded 24 VDC power supply. As the voltage of the

11 power supply decreased so did the apparent Rx pressure. The power supply is an Elma

12 Model #164C5261-2. The power supply was replaced and the system returned to normal.

13 The power supply has been returned to the manufacturer for analysis.

14

15 FACILITY STATUS E (28) | % POWER 999 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) 8206220373 820611 PDR ADOCK 05000271 S PDR

NRC USE ONLY

NAME OF PREPARER Warren P. Murphy PHONE (802) 257-7711

GPO 917-926