1 | A L J M F 2 | 0 0 - 0 0 0 0 0 - 0 0 | 4 1 1 1 1 |
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

REPORT SOURCE | L | 0 5 0 0 0 3 6 4 | 0 6 0 1 8 2 | 0 6 3 0 8 2 |
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 At 1400 on 6/01/82, Containment Atmosphere Activity Monitors R-11 (particulate monitor)
3 and R-12 (gaseous monitor) were declared inoperable when the inboard and outboard pumps
4 tripped due to an erroneous low flow signal. Tech. Spec. 3.4.7.1 requires R-11 and
5 R-12 to be operable. Tech. Spec. 3.4.7.1 action statement requirements were met.
6 Health/safety of the public was not affected.
7
8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
9	C I (11)	E (12)	E (13)	I N S T R U (14)	S (15)	Z (16)

(17) LER NO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO		OCCURRENCE CODE	REPORT TYPE		REVISION NO
	8 2	—	0 2 4	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
E (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	A (25)	X 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 This event was caused by setpoint drift of the flow switches. Following the adjustment
11 of the setpoints, R-11 and R-12 were declared operable at 1615 on 6/01/82.
12
13
14

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
E (28)	1 0 0 (29)	NA	A (31)	Operational Event

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION
Z (42)	

8207090281 820630
PDR ADOCK 05000348
S PDR

PUBLICITY

ISSUED	DESCRIPTION (45)
N (44)	NA

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III PHONE (205) 899-5156