(7-77)

LICENSEE EVENT REPORT

Unit 1

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | T N S N P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 1 (4) | 1 (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 7 (7) | 0 6 0 7 8 2 (8) | 0 7 0 6 8 2 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Unit 1 in mode 1 at 100% power. During the performance of Surveillance Instruction

0 3 | (SI) 144.2 (Control Room Emergency Ventilation Test), the control room emergency

0 4 | ventilation train A failed the minimum system flow rate of 4000 cfm ± 10% and the

0 5 | train A system was declared inoperable. This event caused entry into LCO 3.7.7.

0 6 | There was no effect on public health or safety. Previous occurrences - none.

0 7 |

0 8 |

7 8 9

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	S G (11)	B (12)	A (13)	V A L V E X (14)	B (15)	G (16)
	9 10	11	12	13 18	19	20

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 2	—	0 7 1	/	0 3	L	—	0
	21 22	23	24 26	27	28 29	30	31	32

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
E (18)	F (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	L (25)	X 9 9 9
33	34	35	36	37 40	41	42	43	44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The train A system flow rate was found to be 2800 cfm due primarily to airflow

1 1 | vibration partially closing the manual suction dampers supplying emergency air

1 2 | cleanup fans. The dampers were readjusted and proper airflow was obtained within

1 3 | an hour. A design change request will be submitted to prevent the airflow vibration

1 4 | from altering the damper position.

7 8 9

FACILITY STATUS	% POWER	OTHER STATUS (JO)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5 E (28)	1 0 0 (29)	NA	B (31)	Surveillance testing
7 8 9	10 12	13 44	45 46	80

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6 Z (33)	Z (34)	NA	NA
7 8 9	10 11 44	45	80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
1 7 0 0 0 (37)	Z (38)	NA
7 8 9	11 12 13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
1 8 0 0 0 (40)	NA
7 8 9	11 12 80

LOSS OF OR DAMAGE TO FACILITY

TYPE	DESCRIPTION (43)
1 9 Z (42)	NA
7 8 9	10 80

PUBLICITY

ISSUED	DESCRIPTION (45)
2 0 N (44)	NA
7 8 9	10

8207150584 820706
PDR ADOCK 05000327
S PDR

NRC USE ONLY

68 69

Name of Preparer A. M. Carver /M. R. Harding Phone (615) 751-0349