MISSISSIPPI POWER & LIGHT COMPANY
Helping Build Mississippi
P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

July 15, 1982

NORRIS L. STAMPLEY
SENIOR VICE PRESIDENT

Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

82 JUL 16 A10:26
USNRC REGION II
ATLANTA, GEORGIA

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
Triaxial Forced Balance
Accelerometer Inoperable
Reference: LER 82-003/03 L-0
File 0260/L-835.0
AECM-82/322

On June 16, 1982, Grand Gulf Unit 1 experienced the failure of a triaxial forced balanced accelerometer while performing a surveillance test. Attached is LER 82-003/03 L-0 with supplementary information.

Yours truly,

N L Stampley

NLS:lm
Attachment

cc: Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Taylor (w/a)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Document Control Desk (w/a)
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8207200219 820715
PDR ADOCK 05000416
S PDR

OFFICIAL COPY

IE 22

AE1N1