No. 3-82-10/3L

Mr. R. C. Haynes
Administrator
U.S. Nuclear Regulatory
Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Haynes:

This LER concerns the failure of a drywell pressure recorder. Applicable Tech Spec is 4.2.F.

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | PAPBS3 (2) | 00-000000000 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 050-027 (7) | 061882 (8) | 071382 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During power operation of Unit 3 a downscale failure of the drywell 0-70 PSIG pressure recorder occurred. The redundant 0-70 PSIG pressure recorder was verified operable. Applicable Tech Spec is 4.2.F.

SYSTEM CODE: ID (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: A (13) | COMPONENT CODE: CKTBRK (14) | COMP SUBCODE: X (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 010 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN: A (18) | FUTURE ACTION: F (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0000 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: Y (24) | PRIME COMP. SUPPLIER: A (25) | COMPONENT MANUFACTURER: X999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause of the failure was blown 0.3 AMP fuse installed on the positive side of the power supply to the transmitter circuit board. The fuse was replaced and the recorder returned to service the same day.

FACILITY STATUS: E (28) | % POWER: 100 (29) | OTHER STATUS (30): U/2 Refuel | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): Operator Observation

ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): N/A | LOCATION OF RELEASE (36): N/A

PERSONNEL EXPOSURES — NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION (39): N/A

PERSONNEL INJURIES — NUMBER: 000 (40) | DESCRIPTION (41): N/A

LOSS OF OR DAMAGE TO FACILITY (43) — TYPE: Z (42) | DESCRIPTION: N/A

8207220567 820713
PDR ADOCK 05000278
S PDR

PUBLICITY — ISSUED: N (44) | DESCRIPTION (45): N/A

NRC USE ONLY

NAME OF PREPARER: M. J. Cooney | PHONE: (215) 841-5020

IE22

GPO 917-828