NRC FORM 366
(7-7)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ILZ1S1 (2) | 00-000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE (6) | 05000 3 04 (7) | 08 11 78 (8) | 09 08 78 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operations, the Unit 2 Containment Particulate Ventilation
03 Rad. monitor, 2RE0011, exhibited spurious alarms, and the detector would
04 not respond to the check source. The monitor was taken OOS and shiftly
05 manual grab samples were taken as required by Tech. Spec. 3.14.1.C. There
06 were no safety implications involved and the health and safety of the
07 public was not affected.
08

09 SYSTEM CODE: MC (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: A (13) | COMPONENT CODE: INSTRU (14) | COMP. SUBCODE: S (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 057 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN: B (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 00 00 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB: N (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: W120 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The erratic response was due to a loose signal wire on the "operation"
11 selector switch in the drawer in the control room. The wire was
12 resoldered and the monitor was restored to service. No further corrective
13 action is necessary.
14

15 FACILITY STATUS: E (28) | % POWER: 100 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): Control room annunciator

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

17 PERSONNEL EXPOSURES — NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION (39): NA

18 PERSONNEL INJURIES — NUMBER: 000 (40) | DESCRIPTION (41): NA

19 LOSS OF OR DAMAGE TO FACILITY — TYPE: Z (42) | DESCRIPTION (43): NA

20 PUBLICITY — ISSUED: N (44) | DESCRIPTION (45): NA | NRC USE ONLY

7810170211 S

Glenn Trzyna 746-2084 ext. 251