LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | GAEIH1 (2) | 0000000000 (3) | 41111 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

01 | REPORT SOURCE L (6) | 05003210 (7) | 091578 (8) | 092978 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While at 99% Reactor Power, a refueling floor vent exhaust sensor (D11-N012C) gave
03 a false, high and erratic, indication. At the time of the erroneous signal in the
04 "A" channel, the "B" channel was available and operable. (T.S. 3.2 Table 3.2-8)
05
06
07
08
7 8 9 80

C | SYSTEM CODE BB (11) | CAUSE CODE E (12) | CAUSE SUBCODE G (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 076 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER A37C (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The sensor was giving a false, high and erratic, indication because the G-M tube
11 failed. The type G011 G-M (Pn 167A2554G001) is manufactured by Amperex Electronic
12 Corp. The G-M tube was replaced and the system calibration performed satisfactorily
13 per procedure HNP-1-5114.
14
7 8 9 80

15 | FACILITY STATUS E (28) | % POWER 099 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA
7 8 9 10 80

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY
8 9 10 68 69 80

7810180014 S

NAME OF PREPARER R. T. Nix PHONE: (912) 367-7781
Superintendent of Maintenance