10CFR50.36

SCE&G
A SCANA Company

South Carolina Electric & Gas Company
P.O. Box 88
Jenkinsville, SC 29065
(803) 345-4040

John L. Skolds
Vice President
Nuclear Operations

September 26, 1990 90 OCT 3 A 9:37

Mr. S. D. Ebneter
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 2900
101 Marietta Street, N. W.
Atlanta, Georgia 30323

SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
Special Report (SPR 90-011),
Supplement 1

Dear Mr. Ebneter:

South Carolina Electric & Gas Company submitted Special Report 90-011 on September 12, 1990, documenting the Main Plant Vent High Range Process Monitor, RM-A13, being inoperable due to "spiking" of the monitor. At the time of submittal, the cause of the "spiking" had not been identified and it was noted that a supplemental report would be submitted when the unit was repaired and returned to service.

Repairs were completed and the unit was returned to service on September 13, 1990. The cause of the "spiking" was found to be defective Auxiliary Pre Amp and Low Range Pre Amp cards.

Since this event was initiated by an electrical storm, the Licensee plans no additional corrective action.

Should you have any questions, please call at your convenience.

Very truly yours,

John L. Skolds

RJB/JLS:lcd

c: O. W. Dixon, Jr./T. C. Nichols, Jr.
E. C. Roberts
R. V. Tanner
General Managers
J. J. Hayes, Jr.
C. A. Price
NRC Resident Inspector
J. B. Knotts, Jr.
Marsh & McLennan

Document Control Desk
INPO Records Center
ANI Library
NSRC
NPCF
RTS (ONO 900096)
File (818.05 & 818.08)

9010230249 900926
PDR ADOCK 05000395
S PDC

1/0
IE22