LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | G A F I N 1 (2) | 0 0 0 0 0 0 0 0 0 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

ONT

1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 1 (7) | 1 0 2 1 7 8 (8) | 1 0 2 0 7 8 (9)

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 | While at ~ 82% during a load increase, CMPF was found to be 2.562. The limit is 2.38.

3 | The Reactor Engineer increased flow in an attempt to decrease CMPF. After 2 hours,

4 | the value had not dropped significantly and the APRMs had not been adjusted. After

5 | consultation with other Reactor Engineering Personnel rods were pushed. This reduced

6 | CMPF significantly and the APRMs were adjusted. This does not violate Tech Specs, how-

7 | ever it does violate commitment made to NRC. (See IE Report No. 50-321/78-23, Section

8 | 7).

9 | SYSTEM CODE Z Z (11) | CAUSE CODE A (12) | CAUSE SUBCODE X (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

LER/RO (17) REPORT NUMBER: EVENT YEAR 7 8 | — | SEQUENTIAL REPORT NO. 0 8 8 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT B (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | During a large Zenon transient, CMPF was found to be increasing faster than could be

11 | corrected for using flow increases. The 2 hour time limit had elapsed before further

12 | action was taken. Rods were then pushed and the APRMs adjusted. This resolved the

13 | CMPF problem. No further action was taken.

14 |

FACILITY STATUS F (28) | % POWER 0 8 3 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Engineering Observation

ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

PERSONNEL EXPOSURES: NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

PERSONNEL INJURIES: NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION N/A

PUBLICITY: ISSUED N (43) | DESCRIPTION (44) N/A | NRC USE ONLY

7911030138

NAME OF PREPARER T. V. Greene, Supt. Eng. Services PHONE: (912) 367-7781

GPO 917-326