NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ILZIS2 (2) | 00-00000-00 (3) | 4111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T

01 | REPORT SOURCE L (6) | 05000304 (7) | 092578 (8) | 102578 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operations, pressurizer level 2LT-459 was found to be 6%
03 lower than the other two channels. (ref. Tech. Specs. 3.1.2 and 3.4.2).
04 This is non-conservative for the Pressurizer High Level Reactor Trip per TS
05 table 3.1-1. The associated bistables for this channel were tripped. As
06 the redundant channels were available and operable, the health and safety
07 of the general public was not affected.

0

09 | SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE T (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 066 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER B080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 No cause could be found for this failure. The channel returned to normal
11 with no corrective action. This channel is being monitored to determine
1 the cause of this intermittent failure. Further corrective action will be
13 taken if the monitoring identifies the problem source.

14

15 | FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator Observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

7811240 196

PERSONNEL INJURIES

18 | NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY

19 | TYPE Z (42) | DESCRIPTION (43) NA

PUBLICITY

20 | ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

Paul Hansen