NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C T M N S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 3 6 (7) | 0 7 1 2 8 2 (8) | 0 8 1 0 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During routine surveillance testing, with the plant in Mode 3 and 0 percent power,
03 the 'A' train of the EBFS could not be verified as operable. The plant was operated
04 in accordance with Technical Specification Statement 3.6.5.1 for 28 hours.
05 Similar LER's: None
06
07
08

09 | SYSTEM CODE S C (11) | CAUSE CODE E (12) | CAUSE SUBCODE G (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE P (15) | VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER | EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 3 1 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER H 2 6 C (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The problem was due to the failure of the Honeywell power supply circuit board (#H01)
11 in the Honeywell humidity controller (#W7500). The power supply circuit board was
12 replaced and the system was verified as operable.
13
14

15 | FACILITY STATUS C (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Preventive Maintenance

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

8208180015 820810
PDR ADOCK 05000336
S PDR

NRC USE ONLY

NAME OF PREPARER Gary E. Komosky PHONE (203) 447-1791 (X 4725)