NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N J S G S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 1 1 (7) | 0 7 1 6 8 2 (8) | 0 8 0 4 8 2 (9)

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On July 16, 1982, during routine operation, the Control Operator noticed that No. 21

0 3 | Steam Generator Level Channel II indication was erratic. The channel was declared

0 4 | inoperable, and Limiting Conditions for Operation 3.3.1 Action 7 and 3.3.2 Action 14

0 5 | were entered. All bistables associated with the channel were immediately placed in

0 6 | the tripped condition. The redundant channels were operable throughout the occurrence.

0 7 | The occurrence constituted operation in a degraded mode in accordance with Technical

0 8 | Specification 6.9.1.9.b. (82-066, 82-061, 32-054, 82-052, 82-042)

7 8 9 80

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	I B (11)	E (12)	F (13)	V A L V E X (14)	F (15)	F (16)
	9 10	11	12	13 18	19	20

	(17) LER RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
		8 2	—	0 6 1	/	0 3	L	—	0
		21 22	23	24 26	27	28 29	30	31	32

	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
	B (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	Y (24)	N (25)	R 3 4 4 (26)
	33	34	35	36	37 40	41	42	43	44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The erratic operation of the instrument was due to leakage past the packing on Root

1 1 | Valve 21BF28. The valve was repacked and the leakage stopped. The channel was

1 2 | recalibrated, was returned to service, and the limiting conditions for operation

1 3 | were terminated.

1 4 |

7 8 9 80

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	0 8 3 (29)	NA	A (31)	Operator Observation
	9	10 12	13 44	45 46	80

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA
	9	10 11 44		45 80

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA
	9 11	12 13	80

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA
	9 11	12 80

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA
	9	10 80

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	
	9	10 68	69 80

8208190230 820804
PDR ADOCK 05000311
S PDR

NAME OF PREPARER R. Frahm PHONE: (609) 541-5900 629

NRC-366-926