NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | S C N E E 3 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
0 1 REPORT SOURCE | L (6) | 0 5 0 0 0 2 8 7 (7) | 0 3 2 3 8 1 (8) | 0 4 2 2 8 1 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 1000 hours on March 23, 1981, engineering safeguard valve 3CS-5 failed to
0 3 operate. While attempting to open valve 3CS-5 during testing, the control
0 4 switch indicator indicated the valve to be only partially open. Reactor Build-
0 5 ing integrity will be maintained by valve 3CS-6. During the opening of valve
0 6 3CS-6, administrative controls are maintained to insure capability to isolate
0 7 the valve if necessary. Hence, the health and safety of the public were not
0 8 adversely affected by this incident.

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP SUBCODE	VALVE SUBCODE
0 9	S D (11)	E (12)	A (13)	V A L V O P (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 1 — SEQUENTIAL REPORT NO. 0 0 ~~2~~ 5 / OCCURRENCE CODE 0 ~~5~~ 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18)	X (19)	Z (20)	Z (21)	0 0 0 0	Y (23)	Y (24)	L (25)	~~X 9 9 9~~ L200 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Since the valve could be operated manually, it was determined that the valve
1 1 operator was the primary cause of the problem. Valve 3CS-6 has been failed
1 2 shut, thus isolating valve 3CS-5. During the next Unit 3 outage, this valve/
1 3 operator will be inspected and disassembled to determine why it failed and
1 4 what further corrective actions are needed.

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	1 0 0 (29)	NA	B (31)	Testing of 3CS-5

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	NA	

NAME OF PREPARER J. L. Jones PHONE: (704) 373-8197

8208310079 810427
PDR ADOCK 05000287
S PDR