DMB

TOLEDO EDISON

August 19, 1982

Log No. K82-1230
FILE: RR 2 (NP-33-82-07)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Revision 1 to Licensee Event Report 82-006 including the respective supplemental information sheet. The revision to the report is indicated by a "1" in the left margin of each page.

Please replace your previous copies of this report with the attached revision.

Yours truly,

Terry D. Murray/BCS

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/lmr
Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Walt Rogers
NRC Resident Inspector
Encl: 1 copy

8208310217 820819
PDR ADOCK 05000346
S PDR

AUG 24 1982

IE22