LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP1 (2) | 00-00000-00 (3) | 4111 (4) | (5)
LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT 58

CON'T
01 | REPORT SOURCE L (6) | 05000327 (7) | 073082 (8) | 082782 (9)
DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 1 in mode 1 (100% Rx power), at 2130 CST on 07/30/82, one auxiliary
03 feedwater automatic control valve was declared inoperable due to failure to meet
04 surveillance requirements. This event required entry into action statement "a" of
05 LCO 3.7.1.2. There was no effect upon public health and safety. Previous
06 occurrences - four (SQRO-50-327/82066, 82054, 82009, 82075).
07
08

09 SYSTEM CODE WB (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE VALVOP (14) | COMP. SUBCODE D (15) | VALVE SUBCODE G (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 100 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER M120

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 During performance of SI-166.1 it was found that valve 1-LCV-3-174 would not
11 operate in manual. Investigation revealed a leaking diaphragm at the operator
12 flange. The Masoneilan operator (20000 series) diaphragm was replaced and the
13 valve returned to service at 1600 CST on 08/02/82. No additional corrective action
14 will be taken at this time.

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding Phone: (615) 751-0349

8209020191 820827
PDR ADOCK 05000327
S PDR