Unit 2

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP2 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 | REPORT SOURCE L (6) | 05000328 (7) | 072882 (8) | 082682 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 2 in mode 1 (100% power) at 0835 CST on 07/28/82, one overpower delta
03 temperature channel (2-TI-68-2D) was declared inoperable due to failing low. This
04 event placed the unit in action statement 6 of LCO 3.3.1. There was no effect
05 upon public health and safety. Previous occurrences - none.
06
07
08

09 SYSTEM CODE IA (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE X (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 104 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER F180

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation revealed that the Foxboro Model 66 special R/E resistance to voltage
11 converters had an instrument span shift resulting in the out of tolerance indicators
12 The loop was recalibrated and the bistable setpoints verified to be within the
13 technical specification allowances. The loop was returned to service at 0900 CST
14 on 07/29/82. No further action is planned at this time.

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS NA (30) | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY NA (35) | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) NA

8209020309 820826
PDR ADOCK 05000328
S PDR

NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding Phone: (615) 751-0349