LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | T N S N P 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 2 7 (7) | 0 8 0 3 8 2 (8) | 0 8 3 0 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With unit 1 in mode 1 (Rx power 100%) at 2155 CST on 08/03/82, one RWST level
03 channel (1-LT-63-50) was declared inoperable due to failing low. This event
04 required entry into action statement 18 of LCO 3.3.2.1. There was no effect
05 upon public health and safety. Previous occurrences - none.
06
07
08

09 | SYSTEM CODE I B (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE T (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 9 9 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER B 0 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation revealed a faulty circuit board in the Barton Model 752 transmitter.
11 The circuit board was replaced and the channel returned to service at 2145 CST
12 on 08/05/82. The cause for the faulty circuit board is unknown.
13
14

15 | FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operator observation

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

17 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES

18 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)

19 | TYPE Z (42) | DESCRIPTION NA

8209080511 820830
PDR ADOCK 05000327
S PDR

PUBLICITY

20 | ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding Phone: (615) 751-0349