LICENSEE EVENT REPORT

Unit 1

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | TNSNP1 (2) | 00-00000-00 (3) | 41111 (4) | (5)

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT 57

CON'T

01 | REPORT SOURCE L (6) | 05000327 (7) | 080382 (8) | 080382 (9)

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 Unit 1 in mode 1 at 100% RTP. At 0950 (C), the upper containment personnel airlock

03 inner door locking mechanism failed. This event required entry into LCO 3.6.1.3.

04 There was no effect upon public health or safety. Previous occurrences - four

05 (SQRO-50-327/80121 and SQRO-50-328/81110, 82049, and 82060).

06

07

08

09 SYSTEM CODE SA (11) | CAUSE CODE E (12) | CAUSE SUBCODE C (13) | COMPONENT CODE PENETR (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 097 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER C310

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation found a pin for the door latch bar connecting rod broken at the weld.

11 The weld failure has been attributed to fatigue caused by normal operation of the

12 door. The pin was rewelded to the operating mechanism and the door returned to

13 service on 08/03/82. No additional corrective action is required.

14

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Personnel operating airlock

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

8209080584 820830
PDR ADOCK 05000327
S PDR

NRC USE ONLY

Name of Preparer G. B. Kirk /M. R. Harding Phone (615) 751-0349