GULF STATES UTILITIES COMPANY
POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704
AREA CODE 713 838-6631

October 5, 1982
RBG-13,482
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

RECEIVED
OCT - 7 1982

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-73

On September 2, 1982 Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning improperly installed spring nuts in the General Electric Company supplied Power Generation Control Complex (PGCC) termination cabinets for River Bend Station. GSU has not completed its investigation at this time. An interim or final status report will be provided by January 21, 1983.

Sincerely,

Eddie R Grant

for J. E. Booker
Manager-Engineering & Licensing
River Bend Nuclear Group

JEB/RJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (RRI)

1627

8210130182 821005
PDR ADOCK 05000458
S PDR