NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

LER 82-25/3L

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | VTVYS1 (2) | 00-000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 REPORT SOURCE L (6) | 05000271 (7) | 120182 (8) | 122982 (9)
(60) | (61–68) DOCKET NUMBER | (69–74) EVENT DATE | (75–80) REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During steady state operation, I & C personnel observed the Drywell Atmospheric
03 Temperature recorder, TR-1-149, to be inoperable. This is one of two redundant
04 drywell temperature recorders classified as post-accident instrumentation by
05 T.S. Table 3.2.6. The redundant recorder, 16-19-45 was available and operable.
06 There were no adverse consequences to public health and safety as a result of
07 this event. There have been no previous reportable occurrences of this type.
08

09 SYSTEM CODE ID (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE R (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 025 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER L130 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The apparent cause for the failure of the Leeds and Northrup Speedmax Recorder
11 model 250 was the servo motor logic ground connection. Preventive maintenance
12 was performed on the recorder and the servo motor logic ground was restored. The
13 recorder was calibrated and placed back into service.
14

15 FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Technician Observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION NA

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

8301110323 821229
PDR ADOCK 05000271
S PDR

NRC USE ONLY

NAME OF PREPARER J. P. Pelletier PHONE: (802) 257-7711

GPO 917-926