POWER AUTHORITY OF THE STATE OF NEW YORK
10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019
(212) 397-6200

TRUSTEES
FREDERICK R. CLARK
CHAIRMAN
GEORGE L. INGALLS
VICE CHAIRMAN
RICHARD M. FLYNN
ROBERT I. MILLONZI
WILLIAM F. LUDDY

GEORGE T. BERRY
GENERAL MANAGER
AND CHIEF ENGINEER
LEWIS R. BENNETT
ASSISTANT GENERAL
MANAGER—GENERAL
COUNSEL
WILBUR L. GRONBERG
ASSISTANT GENERAL
MANAGER-ENGINEERING
JOHN W. BOSTON
DIRECTOR OF
POWER OPERATIONS
THOMAS F. McCRANN, JR.
CONTROLLER

December 6, 1978
JNRC-78-61

Director of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Attention: Mr. Thomas A. Ippolito
Operating Reactors Branch No. 3
Division of Operating Reactors

Subject: James A. FitzPatrick Nuclear Power Plant
Rotated Bundle Loading Error Event Analysis
Docket No. 50-333

Dear Sir:

Enclosed are forty (40) copies of General Electric Report NEDO-24129-2, Supplement 2, "Fuel Bundle Loading Error Reanalysis for the James A. FitzPatrick Nuclear Power Plant for Reload No. 2", dated November, 1978.

The Power Authority submitted the results of this analysis to the U.S. Nuclear Regulatory Commission in a letter dated November 16, 1978.

Very truly yours,

Paul J. Early
Assistant Chief Engineer-
Projects

7812120080

P