NRC FORM 366 (12-81)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

APPROVED BY OMB 3150-0011 EXPIRES 4-30-82

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S C N E E 3 (2) | 0 0 - 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE (14) | LICENSE NUMBER (25) | LICENSE TYPE (30) | CAT (58)

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 8 7 (7) | 1 2 1 1 8 2 (8) | 0 1 0 5 8 3 (9)
(60) | DOCKET NUMBER (68) | EVENT DATE (74) | REPORT DATE (80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On December 11, 1982 a steam generator tube leak of approximately .208 gpm was
03 indicated by the Condensate Steam Air Ejector Offgas Radiation Monitor. This
04 constitutes an abnormal degradation of the reactor coolant pressure boundary and
05 is reportable pursuant to Technical Specification 6.6.2.1.a(3). Personnel and
06 systems adequately controlled the event and the releases were well within regu-
07 latory requirements; thus, the health and safety of the public were not affected.
08

09 SYSTEM CODE: C B (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: B (13) | COMPONENT CODE: H T E X C H (14) | COMP. SUBCODE: F (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 1 4 | / | OCCURRENCE CODE 0 1 | REPORT TYPE T | — | REVISION NO. 0

ACTION TAKEN: B (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: A (20) | SHUTDOWN METHOD: A (21) | HOURS (22): 0 2 4 0 | ATTACHMENT SUBMITTED: Y (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER (26): B 0 1 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The apparent cause of the steam generator tube leak was a crack in tube 77-9.
11 This tube and tube 78-2 were removed from service.
12
13
14

15 FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): Operator Observation

16 ACTIVITY RELEASED: M (33) | CONTENT OF RELEASE: M (34) | AMOUNT OF ACTIVITY (35): 1.51c | LOCATION OF RELEASE (36): Vent stack to atmosphere

17 PERSONNEL EXPOSURES: NUMBER 0 4 5 (37) | TYPE E (38) | DESCRIPTION (39): Maintenance Personnel - 6.905 REM

18 PERSONNEL INJURIES: NUMBER 0 0 0 (40) | DESCRIPTION (41): NA

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION (43): NA

8301170528 830105
PDR ADOCK 05000287
S PDR

20 PUBLICITY: ISSUED Z (44) | DESCRIPTION (45): NA

NRC USE ONLY

NAME OF PREPARER John F. Norris, Jr. PHONE (704) 373-2844