Philadelphia, PA

Dear Mr. Grier:

This LER refers to a failure to maintain a firewatch patrol.

S 6/22/79

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A F 0 5 2 0 0 - 0 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0

CON'T 0 1 L 0 5 0 - 0 2 7 7 0 5 2 4 7 9 0 6 2 2 7 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 A firewatch patrol was not conducted while the Unit 2 Recirc MG set fire
0 3 detection system was out of service for construction work, in violation
0 4 of Tech Spec 3.14.C.2d(2). During the 5 hours in which the patrol was
0 5 not being performed, there was no activity in progress which would have
0 6 increased the probability of a fire. Operating personnel were periodical-
0 7 ly in the area completing normal assignments. For these reasons, the safe-
0 8 ty significance of this occurrence is minimal.

0 9 A B A E Z Z Z Z Z Z Z Z

7 9 0 2 9 0 3 L 0

G Z Z Z 0 0 0 0 N N Z Z 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 A failure in communications resulted in the firewatch vacating the monit-
1 1 ored area prior to restoration of the fire detection system. A new pro-
1 2 cedure has subsequently been placed into effect, establishing shift super-
1 3 vision control of firewatch activities. Firewatch personnel and their
1 4 supervision have been instructed in the application of this procedure.

1 5 E 0 5 3 N/A B Routine Inspection

1 6 Z Z N/A N/A

1 7 0 0 0 Z N/A

1 8 0 0 0 N/A

1 9 Z N/A

2 0 N N/A

7906260253 S

M. J. Cooney (215) 841-5020