Mr. Boyce H. Grier, Director
Office of Inspection & Enforcement, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

No. 3-79-15/03L

50-278

S

Dear Mr. Grier:

This LER refers to the setpoint drift of the "A" ADS auto blowdown timer beyond Technical Specification limit in Table 3.2.B.

(5)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 PAPBS3 (2) 00-00-0000-00 (3) 4111 (4) 1 (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T 01 REPORT SOURCE L (6) 050-028 (7) 052379 (8) 062079 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While at power, during surveillance testing the ADS "A" auto blowdown
03 timer trip setting was found to be 13 seconds less than the Tech. Spec.
04 minimum of 90 seconds. Safety significance was minimal since redundant
05 "B" logic was verified operable by surveillance testing. Prior occur-
06 rences were documented in event reports 3-76-39/3L, 2-78-37/3L, and
07 3-79-7/3L.
08

09 SYSTEM CODE SF (11) CAUSE CODE E (12) CAUSE SUBCODE B (13) COMPONENT CODE REYAX (14) COMP SUBCODE H (15) VALVE SUBCODE Z (16)
(17) LER/RO REPORT NUMBER EVENT YEAR 79 — SEQUENTIAL REPORT NO. 015 — OCCURRENCE CODE 03 REPORT TYPE L — REVISION NO. 0
ACTION TAKEN E (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS (22) 0000 ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. Y (24) PRIME COMP. SUPPLIER N (25) COMPONENT MANUFACTURER G080 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the occurrence was setpoint drift of GE Model CR 2820B time
11 delay relay. The time delay relay was readjusted, tested satisfactorily,
12 and returned to service.
13
14

15 FACILITY STATUS E (28) % POWER 090 (29) OTHER STATUS (30) N/A METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION (32) Surveillance Testing

16 ACTIVITY CONTENT Z (34) Z (35) AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 000 Z (38) N/A

18 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 000 N/A

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43) Z (42) N/A

7906260272 S

20 PUBLICITY ISSUED DESCRIPTION (45) N (44) N/A

NAME OF PREPARER M. J. Cooney PHONE (215) 841-5020

FOR USE ONLY