NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | C O F S V 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 2 0 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 0 5 0 0 0 2 6 7 (7) | 0 1 0 4 8 3 (8) | 0 2 0 3 8 3 (9)
DOCKET NUMBER (60–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | With the reactor shutdown, seven unsampled releases were made from the Reactor
03 | Building sump on December 21 and 22. The proportional sampler was inoperable at the
04 | time. This constitutes a degraded mode of LCO 4.8.3(f) and is reportable per Fort
05 | St. Vrain Technical Specification AC 7.5.2(b)3. No accompanying occurrence. No ef-
06 | fect on public health or safety. Similar report is RO 79-14.
07 |
08 |

09 | SYSTEM CODE X X (11) | CAUSE CODE A (12) | CAUSE SUBCODE D (13) | COMPONENT CODE Z Z Z Z Z Z (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 3 | — | SEQUENTIAL REPORT NO. 0 0 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN H (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER Z (25) | COMPONENT MANUFACTURER Z 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | Personnel error. Daily samples were not taken at the regularly scheduled time, and
11 | instructions were not left for relief personnel to obtain the samples during sub-
12 | sequent shifts. Daily sample taking resumed on December 23, 1982. Responsible per-
13 | sonnel were retrained. A design change is in progress to replace the existing pro-
14 | portional sampler with one that is more reliable. No further corrective action is anticipated or required.

15 | FACILITY STATUS G (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Review of System Summary Report

16 | ACTIVITY RELEASED L (33) | CONTENT OF RELEASE P (34) | AMOUNT OF ACTIVITY (35) Less Than Minimum Detectable | LOCATION OF RELEASE (36) Reactor Building Sump to River

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

19 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION N/A

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A

8302150593 830203
PDR ADOCK 05000267
S PDR

NRC USE ONLY

NAME OF PREPARER Charles Fuller PHONE: (303) 785-2224

GPO 891 7-926