LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MAPPS1 (2) | 00-0000-00 (3) | 41111 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 | REPORT SOURCE L (6) | 05000293 (7) | 081382 (8) | 082782 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During recovery from a scram on 8/13/82, (LER 82-023/01T-0) with HPCI being used
03 for pressure control, HPCI tripped after five minutes running due to high reactor
04 water level. After a pump restart, attempts to bring pump past idle speed were un-
05 successful. Eleven manual SRV actuations were therefore necessary to control pressure.
06 This event caused no threat to the general public. NRC was notified at 1553 via
07 ENS.
08

09 SYSTEM CODE CE (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE HTEXCH (14) | COMP. SUBCODE D (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 024 — OCCURRENCE CODE 01 — REPORT TYPE T — REVISION NO. 0

ACTION TAKEN B (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER T147 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 HPCI Gland Seal Condenser gasket failure caused wetting of the HPCI control circuitry.
11 The control circuits were dried and calibrated. Gasket repair was accomplished
12 using an improved version of SIL 129. Four quick-starts under pressure tested both
13 repairs. Modification options for making controls more tolerant of harsh environment
14 are being assessed.

15 FACILITY STATUS C (28) | % POWER 000 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY A (31) | DISCOVERY DESCRIPTION (32) Operator observation

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION N/A

8209080283 820827
PDR ADOCK 05000293
S PDR

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER G. G. Whitney PHONE: 617-746-7900