NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: |1 6 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1		A	R	A	N	0	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7 8	9	LICENSEE CODE					14	15		LICENSE NUMBER								25	26	LICENSE TYPE	30	57	CAT	58						

0	1	REPORT SOURCE	L	6	0	5	0	0	0	3	1	3	7	0	1	0	7	8	3	8	0	2	0	4	8	3	9
7 8		60		61	DOCKET NUMBER								68	69	EVENT DATE				74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0	2	On 1/7/83, while in refueling shutdown, a leak was discovered on the casing vent line for Spent Fuel Pool
0	3	Circulation P-40A. On 1/20/83, a similar leak was discovered on P-40B. Both leaks were in the threaded vent
0	4	pipe to casing connection. In both instances, the leak drained to the Radwaste System. These occurrences
0	5	are reportable per Technical Specification 6.12.3.2.d. Similar occurrences were reported in LER's 82-013 and
0	6	82-014.
0	7	
0	8	

7 8 9 80

0	9	SYSTEM CODE		11	CAUSE CODE	12	CAUSE SUBCODE		13	COMPONENT CODE						14	COMP SUBCODE	15	VALVE SUBCODE	16
7 8		F	C		B		A			P	I	P	E	X	X		A		Z	
		9	10		11		12			13						18	19		20	

LER/RO REPORT NUMBER	EVENT YEAR			SEQUENTIAL REPORT NO.			OCCURRENCE CODE		REPORT TYPE		REVISION NO
17	8	3	-	0	0	2	/	0	3	L	-	0
	21	22	23	24		26	27	28	29	30	31	32

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS				ATTACHMENT SUBMITTED	NPRD-4 FORM SUB	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER			
C	Z	Z	Z	0	0	0	0	N	N	A	Z	9	9	9
33	34	35	36	37			40	41	42	43	44			47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1	0	The cause of the occurrences is believed to be fatigue failure due to vibration and stress in the threaded
1	1	connection. In both cases the vent pipe was replaced. The piping design is being evaluated.
1	2	
1	3	
1	4	

7 8 9 80

1	5	FACILITY STATUS		28	% POWER			29	OTHER STATUS	30	METHOD OF DISCOVERY	31	DISCOVERY DESCRIPTION	32
7 8		H			0	0	0		NA		A		Operator Observation	
		9		10			12	13		44	45	46		80

1	6	ACTIVITY RELEASED		33	CONTENT OF RELEASE		34	AMOUNT OF ACTIVITY	35	LOCATION OF RELEASE	36
7 8		Z			Z			NA		NA	
		9		10			11		44	45	80

1	7	PERSONNEL EXPOSURES NUMBER				TYPE	38	DESCRIPTION	39
7 8		0	0	0	37	Z		NA	
		9		11		12	13		80

1	8	PERSONNEL INJURIES NUMBER				DESCRIPTION	41
7 8		0	0	0	40	NA	
		9		11	12		80

1	9	LOSS OF OR DAMAGE TO FACILITY TYPE		42	DESCRIPTION	43
		Z			NA	

2	0	PUBLICITY ISSUED		44	DESCRIPTION	45	NRC USE ONLY	
7 8		N			NA			
		9		10		68	69	80

NAME OF PREPARER Patrick Rogers PHONE: (501) 964-3100

8302170068 830203
PDR ADOCK 05000313
S PDR