NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NCBEP1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 0503 | 0-0325 (7) | 012683 (8) | 020983 (9)
DOCKET NUMBER (60–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During unit refueling operations, while performing testing required by IE Bulletin
03 82-03, visual examinations done respectively on January 26 and 27 of 1983, revealed
04 single through-wall pin hole cracks in the heat affected zones on the pipe sides of
05 weld B32-recirc-12-BR-H-4, located downstream of the B-loop discharge valve F031B and
06 weld B32-recirc-12-AR-E-2, located downstream of the A-loop discharge valve F031A.
07 These events did not affect the health and safety of the public.
08 Technical Specification 6.9.1.8c

09 | SYSTEM CODE CB (11) | CAUSE CODE E (12) | CAUSE SUBCODE X (13) | COMPONENT CODE PIPEXX (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR 83 | — | SEQUENTIAL REPORT NO. 001 | / | OCCURRENCE CODE 01 | REPORT TYPE T | — | REVISION NO. 0

ACTION TAKEN X (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER A510 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Both pin hole cracks are attributed to IGSCC. These cracks will be repaired using
11 acceptable weld overlay techniques. Future action concerning these failures and a
12 similar one reported in LER 1-83-4 will be addressed in the licensee response to
13 IE Bulletin 82-03.
14

15 | FACILITY STATUS H (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY C (31) | DISCOVERY DESCRIPTION (32) Special Testing

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 | NUMBER 000 (40) | DESCRIPTION (41) NA

8302170183 830209
PDR ADOCK 05000325
S PDR

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr. PHONE: 919-457-9521

GPO 917-926



B-32-REICRC-12-BR-F,-G,-H,-J,-K



B-32-RECIRC-12-AR-A,-B,-C,-D,-E