NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: [| | | | |] (1)   (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| 0 | 1 | C | A | S | 0 | S | 2 | (2) | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | (3) | 4 | 1 | 1 | 1 | 1 | (4) | | (5) |

LICENSEE CODE   LICENSE NUMBER   LICENSE TYPE   CAT

CON'T

| 0 | 1 | REPORT SOURCE | L | (6) | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 1 | (7) | 0 | 8 | 0 | 7 | 8 | 2 | (8) | 0 | 9 | 0 | 3 | 8 | 2 | (9) |

DOCKET NUMBER   EVENT DATE   REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| 0 | 2 | With the plant in Mode 2, turbine isolation valves were declared inoperable due

| 0 | 3 | to inability to place the Turbine Overspeed Protection System (TOPS) in the

| 0 | 4 | exercise mode for valve cycle testing.   These switches are not part of the safety

| 0 | 5 | related trip function, and since the MSIV's and bypasses remained closed throughout

| 0 | 6 | the event, there was no impact on health and safety of plant personnel or the

| 0 | 7 | public.

| 0 | 8 |

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	C D (11)	E (12)	E (13)	V A L V O P (14)	C (15)	Z (16)

	LER/RO REPORT NUMBER (17)	EVENT YEAR		SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
		8 2	—	0 9 0	/	0 3	L	—	0

	ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
	X (18)	X (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	A (25)	M 0 9 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

| 1 | 0 | The inability to place the TOPS in the exercise mode is attributable to

| 1 | 1 | intermittent sticking of contacts on hydraulic dump valve position switches

| 1 | 2 | ZSL 8204-A and ZSL 8205-B.   Jumpers were placed across these switches and cycling

| 1 | 3 | tests completed. No further corrective action is deemed necessary.

| 1 | 4 |

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	B (28)	0 0 0 (29)	NA	B (31)	Surveillance Testing

	ACTIVITY RELEASED (33)	CONTENT OF RELEASE (34)	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z	Z	NA	NA

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	NA

8209140208 820903
PDR ADOCK 05000361
S   PDR

PUBLICITY (45)

	ISSUED	DESCRIPTION
2 0	N (44)	NA

NRC USE ONLY

NAME OF PREPARER _____ H. B. Ray

PHONE: ____ 714/492-7700