NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MAYKR1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 05000029 (7) | 010683 (8) | 020483 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 In Mode 1, while performing a Functional Test of the NRV Main Steam Line
03 Pressure Channels, relays K11A and K11B on MSL #1 did not operate, cont
04 rary to T.S. Table 3.3-2. This is the first occurrence of this nature. T
05 he MSL pressure channels are a 2 of 3 logic system. A trip signal on any
06 2 of 3 channels will close all NRV's. All other MSL pressure channels
07 were functional. There was no adverse effect on the public health and sa
08 fety.
7 8 9 80

09 | SYSTEM CODE CD (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE X (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 83 | — | SEQUENTIAL REPORT NO. 001 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN C (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER X999 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause of the event is attributed to lack of continuity thru Terminal
11 Block T.B. -2.8. The terminal block is a Weidmuller - Klippon type RSF2
12 - screw clamp/spring loaded with disconnect plug. It was replaced in kin
13 d. The channel was functionally tested and found satisfactory. No furthe
14 r corrective action is deemed necessary.
7 8 9 80

15 | FACILITY STATUS E (28) | % POWER 095 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Technician Observation
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES
17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

8302230129 830206
PDR ADOCK 05000029
S PDR

PERSONNEL INJURIES
18 | NUMBER 000 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY (43)
19 | TYPE Z (42) | DESCRIPTION NA
7 8 9 10 80

PUBLICITY
20 | ISSUED N (44) | DESCRIPTION (45) NA | NRC USE ONLY
7 8 9 10 68 69 80

NAME OF PREPARER Donald A. Rice PHONE: (413) 625-1640

GPO 917-926