LICENSEE EVENT REPORT

CONTROL BLOCK: |___|___|___|___|___|___| (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| 0 1 | N Y J A F 1 (2) | 0 0 - 0 0 0 0 - 0 0 0 (3) | 4 1 1 1 1 (4) | | (5) |

7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
| 0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 3 3 (7) | 0 2 0 1 8 3 (8) | 0 2 0 9 8 3 (9) |

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

| 0 2 | During normal operation, while conducting surveillance testing on the reactor low

| 0 3 | water level scram switch 02-3-LIS-101D, setpoint was found less conservative than $\leq$

| 0 4 | 58.0 inches of water as required by T.S. Table 3.1-1. The found value was 60.9 inches

| 0 5 | of water. Other trip channels of the same parameter were available and had setpoints

| 0 6 | within the T.S. The event did not represent a significant hazard to the public

| 0 7 | health and safety.

| 0 8 |

7 8 9 80

| 0 9 | SYSTEM CODE I A (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE I N S T R Y (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16) |

9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 8 3 | — | SEQUENTIAL REPORT NO. 0 0 7 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | — | REVISION NO. 0 |

21 22 23 24 26 27 28 29 30 31 32

| ACTION TAKEN E (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER B 0 8 0 (26) |

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

| 1 0 | Instrument drift was the cause. Corrective action consisted of immediate adjustment

| 1 1 | of the setpoint within the T.S. required value and increasing the test frequency for

| 1 2 | trend observation. No additional action is required.

| 1 3 |

| 1 4 |

7 8 9 80

| 1 5 | FACILITY STATUS E (28) | % POWER 0 9 2 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance |

7 8 9 10 12 13 44 45 46 80

| 1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA |

7 8 9 10 11 44 45 80

| 1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA |

7 8 9 11 12 13 80

| 1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA |

7 8 9 11 12 80

| 1 9 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION NA |

7 8 9 10 80

| 2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA |

7 8 9 10

NRC USE ONLY

|__|__|__|__|__|__|__|__|__|__|__|__|__|
68 69 80

NAME OF PREPARER Hartford Keith   PHONE: 215-342-3840

GPO 917-926