Mr. R. C. Haynes, Director
Office of Inspection & Enforcement, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

No. 2-82-23/3L

Dear Mr. Haynes:

This LER concerns the inoperability of a RCIC subsystem. Applicable Tech Spec is 3.5.D.1.

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | PAPBS2 (2) | 00-000-00 (3) | 4 (4) | 1111 LICENSE TYPE | (5) CAT

CON'T 01 | REPORT SOURCE L (6) | 05000-277 DOCKET NUMBER | (7) EVENT DATE 08/26/82 | (8) REPORT DATE 09/08/82 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While operating at power, the RCIC governor was found to have a
03 positive ground during a routine surveillance test. RCIC was
04 declared inoperable and HPCI was immediately verified operable.
05 Applicable Tech Spec is 3.5.D.1.
06
07
08

09 SYSTEM CODE SF (11) | CAUSE CODE E (12) | CAUSE SUBCODE A (13) | COMPONENT CODE INSTRU (14) | COMP. SUBCODE C (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 023 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER W290 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The ground was caused by a burned out resistor on a Woodward
11 electric governor magnetic servo. The resistor was replaced and
12 RCIC returned to operable condition the following day.
13
14

15 FACILITY STATUS S (28) | % POWER 100 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Test

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) N/A

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION N/A

IE22

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45)

NRC USE ONLY

8209240314 820908
PDR ADOCK 05000277
S PDR

M. J. Cooney — PHONE: (215) 841-5020