LICENSEE EVENT REPORT

CONTROL BLOCK: [| | | | |] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
01	LICENSEE CODE (2)	M I D C C 2
01	LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
01	LICENSE TYPE (4)	4 1 1 1 1
01	CAT (5)	
CON'T 01	REPORT SOURCE (6)	L
01	DOCKET NUMBER (7)	0 5 0 0 0 3 1 6
01	EVENT DATE (8)	0 8 2 4 8 2
01	REPORT DATE (9)	0 9 2 2 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 DURING NORMAL OPERATION, A REACTOR TRIP OCCURRED AS A RESULT OF A FAILURE IN A 120

03 VOLT A.C. VITAL BUS (CRID IV). THIS EVENT WAS NON-CONSERVATIVE WITH RESPECT TO

04 TECHNICAL SPECIFICATION 3.8.2.1. THE PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

05 PREVIOUS OCCURRENCES OF A SIMILAR NATURE INCLUDE: 050-315/79-022, 316/80-020.

06

07

08

Line 09	Value
SYSTEM CODE (11)	E B
CAUSE CODE (12)	E
CAUSE SUBCODE (13)	G
COMPONENT CODE (14)	G E N E R A
COMP. SUBCODE (15)	F
VALVE SUBCODE (16)	Z

LER/RO REPORT NUMBER (17)

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 2	—	0 7 2	/	0 3	L	—	0

ACTION TAKEN (18)	FUTURE ACTION (19)	EFFECT ON PLANT (20)	SHUTDOWN METHOD (21)	HOURS (22)	ATTACHMENT SUBMITTED (23)	NPRD-4 FORM SUB. (24)	PRIME COMP. SUPPLIER (25)	COMPONENT MANUFACTURER (26)
A	Z	A	C	0 0 0 5	N	Y	N	S 2 5 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 INVESTIGATION FOUND THE CAUSE OF THE FAILURE TO BE A BURNED OUT RESISTOR (R1) AND

11 DIODE (D1) ON THE OSCILLATOR BOARD. AN ASSOCIATED FUSE WAS ALSO FOUND BLOWN. THE

12 OSCILLATOR BOARD, MANUFACTURED BY SOLID STATE CONTROLS, WAS REPLACED ALONG WITH THE

13 FUSE. THE SYSTEM WAS VERIFIED TO BE OPERATING CORRECTLY AND RETURNED TO SERVICE.

14

Line 15	Value
FACILITY STATUS (28)	E
% POWER (29)	1 0 0
OTHER STATUS (30)	NA
METHOD OF DISCOVERY (31)	A
DISCOVERY DESCRIPTION (32)	REACTOR TRIP

Line 16	Value
ACTIVITY RELEASED (33)	Z
CONTENT OF RELEASE (34)	Z
AMOUNT OF ACTIVITY (35)	NA
LOCATION OF RELEASE (36)	NA

PERSONNEL EXPOSURES

Line 17	Value
NUMBER (37)	0 0 0
TYPE (38)	Z
DESCRIPTION (39)	NA

PERSONNEL INJURIES

Line 18	Value
NUMBER (40)	0 0 0
DESCRIPTION (41)	NA

LOSS OF OR DAMAGE TO FACILITY (43)

Line 19	Value
TYPE (42)	Z
DESCRIPTION	NA

8210040327 820922
PDR ADOCK 05000316
S PDR

PUBLICITY

Line 20	Value
ISSUED (44)	N
DESCRIPTION (45)	NA

NRC USE ONLY

NAME OF PREPARER R. A. PALMER PHONE 616-465-5901

GPO 917-926