LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | M A P P S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
1 REPORT SOURCE L (6) | 0 5 0 - 0 2 9 3 (7) | 0 8 2 6 8 2 (8) | 0 9 2 4 8 2 (9)
8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 On 8/26/82, both HPCI area smoke detector systems were made inoperable to perform
3 corrective maintenance. T.S. requires one system in the HPCI areas to be operable.
4 A fire patrol was established prior to inoperability. This event caused no
5 threat to the public health and safety.
6
7
8 80
8 9

9 SYSTEM CODE A B (11) | CAUSE CODE E (12) | CAUSE SUBCODE G (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)
8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 (21 22) | — (23) | SEQUENTIAL REPORT NO. 0 3 4 (24 26) | / (27) | OCCURRENCE CODE 0 3 (28 29) | REPORT TYPE L (30) | — (31) | REVISION NO. 0 (32)

ACTION TAKEN B (18) | FUTURE ACTION F (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 (37 40) | ATTACHMENT SUBMITTED N (23) (41) | NPRD-4 FORM SUB. N (24) (42) | PRIME COMP. SUPPLIER L (25) (43) | COMPONENT MANUFACTURER X 9 9 9 (26) (44 47)
33 34 35 36

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 Moisture from a steam leak condensed inside the detectors causing them to give
1 a false smoke indication. The detectors were removed, replaced and
2 functionally tested per procedure. An engineering support request has been
3 issued to provide a long-term fix. The detectors are Simplex Time Recorder Co.
4 Model #4259-35. 80
8 9

5 FACILITY STATUS E (28) | % POWER 1 0 0 (29) | OTHER STATUS (30) NA (44) | METHOD OF DISCOVERY A (31) (46) | DISCOVERY DESCRIPTION (32) Operational Event (80)
8 9 10 12 13 45

6 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA (44) | LOCATION OF RELEASE (36) NA (80)
8 9 10 11 45

7 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA (80)
8 9 11 12 13

8 PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA (80)
8 9 11 12

9 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION NA (80)
8 9 10

PUBLICITY ISSUED N (44) | DESCRIPTION (45) (68 69) | NRC USE ONLY (80)
9 10

B210060030 B20924
PDR ADOCK 05000293
S PDR

NAME OF PREPARER G. G. Whitney PHONE: (617) 746-7900 X241

GPO 917-926