NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | MEMYP1 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T 01 | REPORT SOURCE L (6) | 05000309 (7) | 092982 (8) | 101282 (9)
DOCKET NUMBER (61–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing integrated leak rate procedure 3.17.1 CIS was intentionally allowed
03 to actuate by increasing containment air pressure. CIS/SIAS Steam Generator Blowdown
04 Valve BD-T-32 failed to fully close as required. Since the steam generator membrane
05 barrier was continually intact, the assumed existence of this discrepancy while the
06 plant was at power would not have affected containment isolation. There was no
07 adverse impact on the health and safety of the public.
08

09 SYSTEM CODE SD (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE VALVEX (14) | COMP. SUBCODE F (15) | VALVE SUBCODE D (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 027 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER M120 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A machine screw loose in the steam generator blowdown system became lodged between
11 the disk and seating surface, preventing full closure of the valve. The resulting
12 damage to seat and disk required replacement of both parts. The valve tested
13 satisfactory after repair. Investigation of machine screw origin proved inconclusive.
14

15 FACILITY STATUS H (28) | % POWER 000 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Test

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
17 NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
18 NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
19 TYPE Z (42) | DESCRIPTION NA

PUBLICITY
20 ISSUED N (44) | DESCRIPTION (45) 8210210018 821012 PDR ADOCK 05000309 S PDR | NRC USE ONLY

NAME OF PREPARER Robert H. Nelson PHONE: 207-882-6321

GPO 917-926