NRC FORM 366
(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NJSGS2 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (7–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T
01 | REPORT SOURCE L (6) | 05000311 (7) | 102826 (8) | 102682 (9)
DOCKET NUMBER (60–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On October 2, 1982, during routine operation, a small service water leak of approxi-
03 mately 0.5 GPM was discovered on the cooling coils of No. 23 Containment Fan Coil Unit
04 (CFCU). The unit was isolated and immediate notification of the NRC was performed.
05 No. 23 CFCU was declared inoperable and Action Statement 3.6.2.3.a was entered. Both
06 containment spray systems were operable throughout the occurrence. The event consti-
07 tuted operation in a degraded mode in accordance with Technical Specification 6.9.1.9.b.
08 (82-109, 82-101, 82-100, 82-093, 82-092)

09 SYSTEM CODE: SB (11) | CAUSE CODE: B (12) | CAUSE SUBCODE: A (13) | COMPONENT CODE: HTEXCH (14) | COMP. SUBCODE: C (15) | VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 | — | SEQUENTIAL REPORT NO. 111 | / | OCCURRENCE CODE 01 | REPORT TYPE T | — | REVISION NO. 0

ACTION TAKEN: B (18) | FUTURE ACTION: F (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0000 | ATTACHMENT SUBMITTED: Y (23) | NPRD-4 FORM SUB.: Y (24) | PRIME COMP. SUPPLIER: A (25) | COMPONENT MANUFACTURER: W120 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The leakage was due to erosion of the cooling coils by silt in the service water.
11 The leaking coil was repaired utilizing Belzona metal filler. New design coils will
12 be installed during the next refueling.
13
14

15 FACILITY STATUS: E (28) | % POWER: 082 (29) | OTHER STATUS (30): NA | METHOD OF DISCOVERY: A (31) | DISCOVERY DESCRIPTION (32): Operator Observation

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): NA | LOCATION OF RELEASE (36): NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39): NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41): NA

19 LOSS OF OR DAMAGE TO FACILITY (43): TYPE Z (42) | DESCRIPTION: NA

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45): NA

8210210095 821006
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER: R. Frahm PHONE: 609/935-6000 Ext 3078