CONTROL BLOCK: |___|___|___|___|___|___| (1)   (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | V T V Y S 1 (2) 0 0 - 0 0 0 0 0 - 0 0 (3) 4 1 1 1 1 (4) |___| (5)
LICENSEE CODE   LICENSE NUMBER   LICENSE TYPE   CAT

CON'T
0 1 REPORT SOURCE L (6) 0 5 0 0 0 2 7 1 (7) 0 9 1 4 8 2 (8) 1 0 1 2 8 2 (9)
DOCKET NUMBER   EVENT DATE   REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing monthly pump operability surveillance on the RCIC system, the |

0 3 | RCIC turbine tripped on overspeed. RCIC was declared inoperable and alternate |

0 4 | testing of the HPCI pump commenced per Tech. Spec. 4.5.G.2. There were no |

0 5 | consequences to the public health and safety. There were no previous reportable |

0 6 | occurrences of this type. |

0 7 | |

0 8 | |

0 9 SYSTEM CODE C E (11) CAUSE CODE E (12) CAUSE SUBCODE G (13) COMPONENT CODE I N S T R U (14) COMP. SUBCODE C (15) VALVE SUBCODE Z (16)

(17) LER RO REPORT NUMBER EVENT YEAR 8 2 SEQUENTIAL REPORT NO. 0 2 1 OCCURRENCE CODE / REPORT TYPE 0 3 L REVISION NO. 0

ACTION TAKEN C (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS (22) 0 0 0 0 ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. Y (24) PRIME COMP. SUPPLIER N (25) COMPONENT MANUFACTURER W 2 9 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this event was the failure of the electronic governor module (EGM). |

1 1 | 'The EGM was replaced and the system tested satisfactorily. Further investigation |

1 2 | found a bad transistor in the tach generator portion of the EGM. The component |

1 3 | was manufactured by Woodward Governor Part #8270-849. |

1 4 | |

1 5 FACILITY STATUS E (28) % POWER 1 0 0 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY B (31) DISCOVERY DESCRIPTION (32) Monthly Surveillance

1 6 ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
1 7 NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION (39) NA

PERSONNEL INJURIES
1 8 NUMBER 0 0 0 (40) DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
1 9 TYPE Z (42) DESCRIPTION NA

PUBLICITY
2 0 ISSUED N (44) DESCRIPTION (45) NA

8210210214 821012
PDR ADOCK 05000271
S   PDR

NRC USE ONLY
|___|___|___|___|___|___|___|___|___|___|___|___|

NAME OF PREPARER ___J. P. Pelletier___   PHONE: 802-257-7711

GPO 91 7-926