NRC FORM 366 (12-81)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

APPROVED BY OMB 3150-0011 EXPIRES 4-30-82

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | SCVCS1 (2) | 00-0000-00 (3) | 41000 (4) | (5)

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 REPORT SOURCE | L (6) | 05000395 (7) | 091582 (8) | 101582 (9)

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 In performing surveillance testing on RHR/COP pressure transmitter (PT 402) with
03 the "B" train RHR in operation, a test signal was generated. The "B" train RHR
04 headed isolation valve (XVG 8702B) shut and isolated suction. The "B" RHR pump
05 was manually tripped. There was no adverse consequence since the RHR pumps are
06 equipped with a minimum flow recirc. line. Also, 8702B was reopened and the RHR
07 pump restarted within one minute.
08

09 SYSTEM CODE: CF (11) | CAUSE CODE: D (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: VALVEX (14) | COMP. SUBCODE: E (15) | VALVE SUBCODE: D (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 82 — SEQUENTIAL REPORT NO. 004 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN: E (18) | FUTURE ACTION: G (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0000 | ATTACHMENT SUBMITTED: Y (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER (26): W120

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The associated surveillance test procedure (STP-340.008) did not adequately
11 address the concern that the test would definitely cause closure of the RHR
12 suction isolation valves. The corrective action taken is the revision of
13 STP-340.008 to line up alternate RHR train with its associated suction isolation
14 valve locked out.

15 FACILITY STATUS: B (28) | % POWER: 000 (29) | OTHER STATUS (30): N/A | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): OPERATOR OBSERVATION

16 ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): N/A | LOCATION OF RELEASE (36): N/A

17 PERSONNEL EXPOSURES — NUMBER: 000 (37) | TYPE: Z (38) | DESCRIPTION (39): N/A

18 PERSONNEL INJURIES — NUMBER: 000 (40) | DESCRIPTION (41): N/A

19 LOSS OF OR DAMAGE TO FACILITY — TYPE: Z (42) | DESCRIPTION (43): N/A

8210220443 821015
PDR ADOCK 05000395
S PDR

20 PUBLICITY — ISSUED: N (44) | DESCRIPTION (45): N/A

NRC USE ONLY

NAME OF PREPARER Curtis Fields PHONE: (803) 345-5209