NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Line	Field	Value
01	LICENSEE CODE (2)	G A E I H 2
01	LICENSE NUMBER (3)	0 0 - 0 0 0 0 0 - 0 0
01	LICENSE TYPE (4)	4 1 1 1 1
01	CAT (5)	
01 CON'T	REPORT SOURCE (6)	L
01	DOCKET NUMBER (7)	0 5 0 0 0 3 6 6
01	EVENT DATE (8)	0 9 1 8 8 2
01	REPORT DATE (9)	1 0 1 2 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With the reactor operating at 63% power, the STA ran P-1 (periodic core
03 performance log) without the benefit of OD-1 (LPRM calibration). The
04 P-1 subsequently indicated a FRTP of .627 and a CMFLPD of .653. OD-1
05 was not run due to "C" Tip machine being inop. Corrective action was
06 initiated within the required time span. The health and safety of the
07 public were not affected by this event. This is a repetitive event as
08 last reported in LER 50-366/1982-086.

Line	Field	Value
09	SYSTEM CODE (11)	Z Z
09	CAUSE CODE (12)	X
09	CAUSE SUBCODE (13)	Z
09	COMPONENT CODE (14)	Z Z Z Z Z Z
09	COMP. SUBCODE (15)	Z
09	VALVE SUBCODE (16)	Z

LER/RO REPORT NUMBER (17)

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 2	—	1 1 1	/	0 3	L	—	0

ACTION TAKEN (18)	FUTURE ACTION (19)	EFFECT ON PLANT (20)	SHUTDOWN METHOD (21)	HOURS (22)	ATTACHMENT SUBMITTED (23)	NPRD-4 FORM SUB. (24)	PRIME COMP. SUPPLIER (25)	COMPONENT MANUFACTURER (26)
E	X	Z	Z	0 0 0 0	Y	N	Z	Z 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Control rod withdrawal in areas of low xenon concentration and a poor
11 base distribution on the P-1 contributed to the high peak. APRM gains
12 were adjusted to read CMFLPD within 15 minutes. Efforts to run OD-1
13 will be made and control rod patterns will be selected to minimize the
14 peak, prior to initiating P-1.

Line	FACILITY STATUS (28)	% POWER (29)	OTHER STATUS (30)	METHOD OF DISCOVERY (31)	DISCOVERY DESCRIPTION (32)
15	C	0 6 3	NA	A	STA Observation of P-1

Line	ACTIVITY RELEASED (33)	CONTENT OF RELEASE (34)	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16	Z	Z	NA	NA

PERSONNEL EXPOSURES

Line	NUMBER (37)	TYPE (38)	DESCRIPTION (39)
17	0 0 0	Z	NA

PERSONNEL INJURIES

Line	NUMBER (40)	DESCRIPTION (41)
18	0 0 0	NA

LOSS OF OR DAMAGE TO FACILITY (43)

Line	TYPE (42)	DESCRIPTION
19	Z	NA

8210290381 821012
PDR ADOCK 05000366
S PDR

PUBLICITY

Line	ISSUED (44)	DESCRIPTION (45)	NRC USE ONLY
20	N	NA	

NAME OF PREPARER H. L. Sumner - Supt. Plt. Eng. Serv. PHONE: 912-367-7851

GPO 917-926