(7-77) U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C A S 0 S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE (9-14) | LICENSE NUMBER (15-25) | LICENSE TYPE (26-30) | CAT (57-58)

CON'T

0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 1 (7) | 0 9 2 1 8 2 (8) | 1 0 2 1 8 2 (9)

DOCKET NUMBER (60-68) | EVENT DATE (69-74) | REPORT DATE (75-80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | With the plant in Mode 1, after tripping the turbine during turbine generator

0 3 | excitation testing, turbine control valves 2MV-2200 C and G failed to close fully

0 4 | and were declared inoperable. Since turbine stop valves were verified shut,

0 5 | isolating the turbine from the steam supply, there was no impact on health and

0 6 | safety of plant personnel or the public.

0 7 |

0 8 |

0 9 | SYSTEM CODE H A (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE V A L V E X (14) | COMP. SUBCODE X (15) | VALVE SUBCODE X (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | SEQUENTIAL REPORT NO. 1 2 0 | OCCURRENCE CODE 0 3 | REPORT TYPE L | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER X 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Inability of the valves to close fully was attributable to mechanical binding

1 1 | between the valve spindle and the spindle bushing of these electro-hydraulic valves.

1 2 | The valve spindle and spindle bushings were replaced. No other corrective

1 3 | action is warranted.

1 4 |

1 5 | FACILITY STATUS B (28) | % POWER 0 0 0 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Startup Testing

1 6 | ACTIVITY RELEASED Z (33) | OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA

8211020294 821021
PDR ADOCK 05000361
S PDR

2 0 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER H. B. Ray PHONE 714/492-7700