NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I L Z I S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
0 1 | REPORT SOURCE L (6) | 0 5 0 0 0 2 9 5 (7) | 0 9 2 9 8 2 (8) | 1 0 2 9 8 2 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During monthly surveillance (PT-210A), two switches controlling the
0 3 standby instrument air (IA) compressors (0AV 070-0A, 0AV 071-0B) were
0 4 found turned off. This violates TS 4.17.2.1. The receiver tanks and
0 5 IA were available since the last surveillance, so the affected HVAC
0 6 dampers would have operated leaving the health and safety of the public
0 7 unaffected. No previous occurrences.
0 8

0 9 | SYSTEM CODE A A (11) | CAUSE CODE A (12) | CAUSE SUBCODE X (13) | COMPONENT CODE B L O W E R (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 | — | SEQUENTIAL REPORT NO. 0 3 2 | / | OCCURRENCE CODE 0 3 | REPORT TYPE L | - | REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION X (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0 0 0 0 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER A (25) | COMPONENT MANUFACTURER 0 1 0 8 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause for the air compressor switches being off cannot be deter-
1 1 mined. A sign has been posted by the compressor switches to alert
1 2 personnel as to the proper mode. No further action required.
1 3
1 4

1 5 | FACILITY STATUS E (28) | % POWER 0 9 9 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Operating Staff Observation

1 6 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES
1 7 | NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES
1 8 | NUMBER 0 0 0 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)
1 9 | TYPE Z (42) | DESCRIPTION NA

PUBLICITY
2 0 | ISSUED N (44) | DESCRIPTION (45) 8211050130 820129 PDR ADOCK 05000295 S PDR | NRC USE ONLY

NAME OF PREPARER F. H. Stahmer PHONE: 312-746-2084 ext.316